INSPECTION REPORT

Partial Complete XXX Exploration Inspection Date: 01/24/2003/ Time: 9:30 – 12:30
Date of Last Inspection: 12/19/2002

Mine Name: West Ridge Mine	County: Carbon	Permit Number: <u>C/007/041</u>						
Permittee and/or Operator's Name: West Ridge Resources, Inc.								
Business Address: P.O. Box 1077, Price, Utah	n 84501							
Company Official(s): Gary Gray								
State Official(s): Karl R. Houskeeper	Federa	al Official(s): None						
Weather Conditions: Clear, Temp 39°F								
Type of Mining Activity: Underground XXX	X Surface Prep F	lantOther						
Existing Acreage: Permitted 4307.63 Distr	urbed 29.06 Regrade	d Seeded						
Status: Active								

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	[X]		[X]	
3.	TOPSOIL	[X]		\Box	
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box	[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		\Box	
d.	WATER MONITORING	[X]	\Box	[X]	\Box
e.	EFFLUENT LIMITATIONS	[X]		[<u>X]</u> [X]	
5.	EXPLOSIVES	[X]			
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]		\Box	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[X]		
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]			
10.	SLIDES AND OTHER DAMAGE	[X]			
11.	CONTEMPORANEOUS RECLAMATION	[X]		\Box	
12.	BACKFILLING AND GRADING	[X]			
13.	REVEGETATION	[X]			
14.	SUBSIDENCE CONTROL	[X]		\Box	
15.	CESSATION OF OPERATIONS	[X]			
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]		[X]	
b.	DRAINAGE CONTROLS	[X]			
17.	OTHER TRANSPORTATION FACILITIES	[X]			
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]		\Box	
19.	AVS CHECK (4th Quarter- April, May, June)	[X]			
20.	AIR QUALITY PERMIT	[X]		[X]	
21.	BONDING & INSURANCE	[X]		[X]	

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/041</u> DATE OF INSPECTION: <u>01/24/2003</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The current DOGM permit was re-issued effective 02/15/2002, to include the Whitmore Extension, and expires 04/01/2004. The reclamation agreement (Exhibit A) reflects the permit area information prior to the approval of the Whitmore Canyon Extension and should be updated to reflect the current permit area acreage information. Other documents reviewed included the following:

- -Certificate of Insurance issued 07/01/2002 and terminates 07/01/2003.
- -Reclamation agreement is dated April 1999 and signed by both parties.
- -UPDES permit UTG040013 effective 01/01/1999 and expires midnight 04/30/2003.
- -Air Quality permit DAQE-055-99, issued January 14, 1999.
- -SPCC Plan dated 12/28/2000.

Reminded the operator of the expiration date associated with the UPDES permit. The operator indicated that the appropriate information and request have been submitted to Water Quality to renew this permit.

NOV #N02-49-2-1, relative to mine water discharge being diverted into the sediment pond, has been modified to extend the abatement date to February 03, 2003. The extension was granted to allow the Division time to review a plan submitted by the operator that if approved would allow the mine water to utilize existing diversions, culverts and the sediment pond for treatment of the mine water.

2. SIGNS AND MARKERS

The mine permit ID signs were observed at the pump house and the entrance to the mine site. The ID signs contained all the required information.

Other signs observed during the inspection met the coal rules.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were overviewed, some melting and freezing has occurred leaving ice in the diversions. The diversions are in good repair and are able to function as designed.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The 2002 annual sediment pond inspection was done on November 20,2002 and P.E. certified on the same day. No structural instability was noted in the report. The report contained the following information:

- Existing Storage Capacity, 6.711 acre-feet.
- Water Depth Upper Cell (Cell A), 4.5 feet.
- Water Depth Lower Cell (Cell B), Dry.
- Sediment Elevation Cell, A 6939.3 feet, and Cell B 6926.8 feet.
- 60% Sediment Elevation, Cell A 6942.8 feet, and Cell B 6928.8 feet.
- Primary Spillway Elevation, Cell A 6952.5 feet, and Cell B 6937.0 feet.
- Emergency Spillway Elevation, Cell A 6952.5 feet, and Cell B 6938.0 feet.
- Existing Sediment Capacity (to cleanout), Cell A 0.859 acre-feet, Cell B 0.408 acre-feet.

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/041</u> DATE OF INSPECTION: <u>01/24/2003</u>

4D. HYDROLOGIC BALANCE: WATER MONITORING

Fourth quarter 2002 water quality information has been entered into the EDI website and has been uploaded. Water monitoring is current.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

The November 2002 Discharge Monitoring Reports (DMR's) were reviewed during the inspection. No discharge occurred from either the 001 outfall (sediment pond), or the 002 outfall (Mine Water) during November 2002.

8. NONCOAL WASTE

Minimal amounts of noncoal waste were identified in one diversion and a pad area. The operator made note of the areas and will have the waste picked up and placed in the approved storage area.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

The Division Order relative to the classification of roads has been extended to February 17, 2002.

20. AIR QUALITY PERMIT

The air quality permit DAQE-055-99 referenced above remains in effect.

21. BONDING AND INSURANCE

The insurance referenced in item #1 above is through Pacific Indemnity Co., policy #3710-95-30-DAL. The insurance has explosion coverage, met the minimum requirements, listed the Division as the certificate holder, and has the proper language on the notification policy.

Bond No. 91-B-54926, issued 03/19/1999 is for \$2,117,000 from National Union Fire Insurance Company.

Inspector's Signature:			Date:	January	24,	2003
	Karl R. Houskeeper	#49				

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Gary Gray, West Ridge
Price Field office
O:\007041.WR\Compliance\2003\c 0124.doc